

**ENGINEERING CHANGE NOTE:**

ECN #:

360.2

ASSEMBLY: BMW4041D**DESCRIPTION:** MW4-QDC Quad Digital Channel Card**New Assembly:****DATE:** 17/10/00**Current Assy Rev:** F**Current Schematic Rev:****New Assy Rev:** G 1G**New Schematic Rev:**

☒ CMS BOMs Updated ☒ Excel BOMs Updated ☐ Subcontractor Records Updated **Compatibility Maintained:** Yes

IMPLEMENTATION INFORMATION:

- | | | | |
|---|--|---------------------------------------|--------------------------------------|
| <input type="radio"/> Safety Issue | <input type="radio"/> UL Compliance Issue | <input type="radio"/> New Feature | <input type="radio"/> Cost Reduction |
| <input checked="" type="radio"/> Bug Fix | <input type="radio"/> EMC Compliance Issue | <input type="radio"/> Quality Issue | |
| <input type="radio"/> Reliability Reasons | <input type="radio"/> Software Change | <input type="radio"/> Cosmetic Change | |

REASON FOR CHANGE:

Correct mistakes in the BOM

Improve DSP and ADV clock signals

DETAILS OF CHANGE:

1. Fit a 1k5 SMD 0603 resistor Fairlight P/N RMD7490 at each of the following locations: R5, R15, R307, R310, R314, R316 on QDC rev4 boards.
2. Fit a 220r SMD 0603 resistor Fairlight P/N RMD4319 at location R313
3. On solder side, cut track from U145/4 to R307 (This is a very short track).
Reconnect same pad of R307 to U145/3
4. Inspect ICs U112-U115 and U123-U126 (8 x CY7C024 DPRAMS)

If any of these 8 parts have a speed grade = 25 ns then add a solder blob across J5 and place a assembly revision label after the blank PCB P/N on the card, marked "1G", so it looks as follow: "BMW4041D-1G"

If all 8 parts are speed grade 15 or 20 ns then there should be no solder blob on J5 and place a assembly revision label after the blank PCB P/N on the card, marked "G", so it looks as follow: "BMW4041D-G"

ECN360.2 is a correction to ECN 360.1: Changed "G" to "G 1G" in NEW ASSY REV