

ECN # 385

Page 1 of 1

**ENGINEERING CHANGE NOTE:**

mfx3

ECN #:

385

**ASSEMBLY:** BMW4061**DESCRIPTION:** MW4-AES1 Digital Input/Output**New Assembly:****DATE:** 06/09/00**Current Assy Rev:** B**Current Schematic Rev:** 1.1 2.0**New Assy Rev:** C**New Schematic Rev:** 1.2 2.1

☐ CMS BOMs Updated ☒ Excel BOMs Updated ☒ Subcontractor Records Updated **Compatibility Maintained:** Yes

**IMPLEMENTATION INFORMATION:**

- ☐ Safety Issue ☐ UL Compliance Issue ☐ New Feature ☐ Cost Reduction  
☒ Bug Fix ☐ EMC Compliance Issue ☐ Quality Issue  
☐ Reliability Reasons ☐ Software Change ☐ Cosmetic Change

**REASON FOR CHANGE:**

To fix noise on AES inputs

(This change applies to both Rev A &amp; Rev B PCBs)

**DETAILS OF CHANGE:**

Remove IC 74FCT244 at location U16.

Solder an IC 74LVC244 (P/N SSQ5981) at location U16.

Cut track from U16 pin 20 (between solder pad and via).

Connect a mod wire from U16/20 to U14/37.

Connect a 10nF SMD0805 cap (P/N CCE1338) between U16/1 and U16/20 with minimum length bare hookup wire.

For Rev A PCB: Put a solder blob across J3 and remove solder blob across J4 to raise the R&amp;D Revision Code to 1.2.

For Rev B PCB: Put a solder blob across J4 to raise the R&amp;D Revision Code to 2.1.

Place a assembly revision label on the card, marked "C", after the blank PCB P/N so it reads as " BMW4061A-C" (For Rev A PCB) and " BMW4061B-C" (For Rev B PCB).

HW or Project Engineer.....

R&amp;D or Project Manager.....