ECN#

437.1

Page 1 of 1

Join Light Engineering Change Note:



ECN#:

#: 43

ASSEMBLY: BMW4011 **DESCRIPTION:** MW4-PXY CPU CARD New Assembly: **DATE:** 08/11/01 Current Assy Rev: U1 **Current Schematic Rev:** 5.14 New Assy Rev: V **New Schematic Rev:** 6.0 NOTE: THIS ECN REPLACES ECN437 BECAUSE OF ERROR IN SOLDER BLOB REFERENCES Details (Line Item 6). THIS ECN DOES NOT AFFECT PCB-s REV 5 AND LOWER. THERE ARE NO FUNCTIONAL CHANGES TO THE BOARD. Excel BOMs Updated O CMS BOMs Updated Subcontractor Records Updated Compatibility Maintained: Yes IMPLEMENTATION INFORMATION: Safety Issue **UL Compliance Issue** New Feature Cost Reduction **Bug Fix EMC Compliance Issue** Ouality Issue

REASON FOR CHANGE:

Reliability Reasons

- 1. Introduction of Rev 6 (Rev F) PCB which incorporates all ECN-s applied to Rev 5 board.
- 2. Value changes of R95 and R96 and routing and layer changes of some clocks reduces EMI level.
- 3. Introduction of a new method of machine readable modification levels: different resistor configurations used on Rev 5 have been replaced by the selective application of solder blobs in a binary code.

Cosmetic Change

DETAILS OF CHANGE:

- 1. Blank PCB Rev 5 (BMW4011E) replaced with PCB Rev 6 (BMW4011F).
- 2. Card Revision Resistors R128, R134, R137 and R138 are now permanently loaded.
- 3. Card Revision Resistors R127, R133, R135 and R136 are permanently removed.
- 4. Resistors R95 and R96 vlue changed from 0R to 33R.
- 5. Two 3-Pin Headers (JMH0272) and two Shorting Plugs (JMJ6765) added to locations J25 and J26.
- 6. Apply Solder Blobs across the pads of SB1, SB2, SB3 and SB4.

○ Software Change

7. Label the Card with the Part Number and Revision label that reads: BMW4011F-V.

.

NOTE TO SUBCONTRACTORS: No effect on WIP. Production Documentation and Costing to be updated.

NOTE TO PRODUCTION: No effect on Stock or WIP.

.

NOTE TO THE FIELD SERVICE: No action required.