

 **ENGINEERING CHANGE NOTE:** 

ECN #:532

ASSEMBLY: AMW4050-A	DESCRIPTION: MW4-Rack Assembly
New Assembly: AMW4050-A	DATE: 16/12/02
Current Assy Rev: A	Current Schematic Rev:
New Assy Rev: A	New Schematic Rev:

☐ CMS BOMs Updated☐ Excel BOMs Updated☐ Subcontractor Records Updated

Compatibility Maintained: Yes

IMPLEMENTATION INFORMATION:

- ☐ Safety Issue☐ UL Compliance Issue☐ New Feature☐ Cost Reduction
- ☐ Bug Fix☐ EMC Compliance Issue☐ Quality Issue
- ☐ Reliability Reasons☐ Software Change☐ Cosmetic Change

REASON FOR CHANGE:

PSU may get dislodged in transport

DETAILS OF CHANGE:

1. Replace two M3x8 Pozi Screws and 2 M3 Flat Washers used to secure the PSU in its location with two M3x8 Button Head Hex Socket Screws (FSC5376), two M3 Crinkle Washers and two PSU Retaing Plates (MMW4074-A).

NOTE TO PRODUCTION: Modify all existing Stock and WIP

NOTE TO FIELD SERVICE: If a customer requires to secure the PSU for the air transport of the Rack a PSU Retention Kit ZZK2611 can be ordered from Fairlight Sydney