

ECN #

1005

Page 1 of 1



## ENGINEERING CHANGE NOTE:

ECN #:

1005

**ASSEMBLY:** BMW4001C-G**NEW ASSEMBLY:** BMW4001C-H**CURRENT REV:** G**NEW REV:** H**DESCRIPTION:** MW4-BPR Backplane**DATE:** 19/04/2004**REASON FOR CHANGE:**

- |   |  |  |                                      |
|---|--|--|--------------------------------------|
| <input type="radio"/> Safety Issue        | <input type="radio"/> UL Compliance Issue  | <input checked="" type="radio"/> New Feature | <input type="radio"/> Cost Reduction |
| <input type="radio"/> Bug Fix             | <input type="radio"/> EMC Compliance Issue | <input type="radio"/> Quality Issue          |                                      |
| <input type="radio"/> Reliability Reasons | <input type="radio"/> Software Change      | <input type="radio"/> Cosmetic Change        |                                      |

To allow 5 QDC cards to be plugged in to the BPR

**COMPATIBILITY MAINTAINED:** Yes**DETAILS OF CHANGE:**

1. Load one more connector P/N JPM9531 at location CN24
2. Load two more connectors P/N JPM5147 at location CN22 and CN23
3. New Board Assembly Revision: BMW4001C-H

.  
. .  
. .

NOTE TO SUBCONTRACTORS: Modify all work in progress

.  
. .  
. .  
. .

**SIGNATURES:****Engineer:****Implementor:****Date:****Operations Manager:**