ECN#

340.1

Page 1 of 1

twirlight ENGI

ENGINEERING CHANGE NOTE:

mfx3

ECN #: 340

| ASSEMBLY: F New Assembly: | 3MW4032 | DESCRIPTION: DATE: | MW4-IOC1 Input Output Card 1 24/05/00 |
|--|--------------------------------|-----------------------------|--|
| • | | | |
| Current Assy Rev: I | D1 (| Current Schematic Rev: | 3.3 |
| New Assy Rev: 1 | <u> </u> | New Schematic Rev: | 4.0 |
| CMS BOMs Updated | Excel BOMs Updated | Subcontractor Records Updat | ted Compatibility Maintained: Yes |
| IMPLEMENTATION INFORMATION: | | | |
| ○ Safety Issue | UL Compliance Issue | New Feature | ○ Cost Reduction |
| O Bug Fix | O EMC Compliance Issue | O Quality Issue | |
| Reliability Reasons | _ | Cosmetic Change | |
| REASON FOR CHANGE: | | | |
| Release of IOC1 Rev 4 PCB | | | |
| DETAILS OF CHANGE: | | | |
| Rev 4 PCB is equivalent to Rev 3.3 (Assembly Rev E) and incorporates ECNs 338.2, 342.1 & 361 | | | |
| The footprints for U10 & U11 have been corrected. | | | |
| After the board has been loaded place a assembly revision label on the card, marked "E", after the blank PCB P/N so it looks as follows BMW4032D-E | | | |
| ECN 340.1 is a | correction to ECN 340: Correct | ed current schematic revisi | on |