ECN#

346

Page 1 of 1

Avirlight ENGINEERING CHANGE NOTE:



ECN#: 34

				_
ASSEMBLY: BN New Assembly: BN Current Assy Rev: C New Assy Rev: D	MW4001 MW4001C-D	DESCRIPTION: DATE: Current Schematic Rev: New Schematic Rev:	MW4-BPR Backplane 31/03/00	
O CMS BOMs Updated	• Excel BOMs Updated	Subcontractor Records Up	dated Compatibility Maintained: Yes	
IMPLEMENTATION IN Safety Issue Bug Fix Reliability Reasons	NFORMATION: UL Compliance Issue EMC Compliance Issue Software Change	New Feature Quality Issue Cosmetic Change	• Cost Reduction	
REASON FOR CHANGE: Slots 1,3,5,7 and 9 are the only ones required to be populated the other slots are to be left vacant.				
DETAILS OF CHANGE:				

- $1.\ \ Do\ NOT\ populate\ PCB\ locations\ CN4\ CN5\ CN10\ CN11\ CN16\ CN17\ CN22\ CN23\ with\ JPM5147\ (Compact\ PCI\ Male\ STR\ Type\ B).$
- 2. Do NOT populate PCB locations CN6 CN12 CN18 CN24 with JPM9531 (Compact PCI Male STR Type A).
- 3. JP8 was accidently left off the BOM and should be loaded with P/N JMH6204, Connector 5 Pin Header, Straight, Friction lock, PCB Straight through hole, U.L Recognised, Molex (22-27-2051)