ECN#

370

Page 1 of 1

trivlight ENGIN

ENGINEERING CHANGE NOTE:



ECN #:

ASSEMBLY: 1 New Assembly:	BMFX010K	DESCRIPTION: DATE:	MW4-MR1 MFX010 Console CPU Card 06/06/00
Current Assy Rev:	M C	urrent Schematic Rev:	
New Assy Rev: 1	N	New Schematic Rev:	
(Note that the MW4-RK1 board must be Rev E (3.1) or higher if in Merlin console.)			
CMS BOMs Updated			
IMPLEMENTATION INFORMATION:			
Safety Issue Bug Fix Reliability Reasons	 UL Compliance Issue EMC Compliance Issue Software Change 	New FeatureQuality IssueCosmetic Change	○ Cost Reduction
REASON FOR CHANGE: Reduce radiated emissions on cables connected to 9 Pin serial port of console			

DETAILS OF CHANGE:

- 1. Remove connector J4 (COND7000) from PCB.
- 2. Replace connector with the following;

JDM5789 - CON DB9M PCB R/A FILTERED

3. Mark PCB revision N to reflect the change of assembly.