ECN#

373

Page 1 of 1

## Anielight engineering change note:



ECN #: 37.

ASSEMBLY: New Assembly:	BMW4001C-D	DESCRIPTION: DATE:	MW4-BPR Backplane 07/07/00
<b>Current Assy Rev:</b>		Current Schematic Rev:	
New Assy Rev:		New Schematic Rev:	
This ECN is to formalise existing practice. The assembly revision has not been changed.			
CMS BOMs Updated	Excel BOMs Updated	Subcontractor Records Update	ced Compatibility Maintained: Yes
IMPLEMENTATION INFORMATION:			
<ul><li>Safety Issue</li><li>● Bug Fix</li><li>Reliability Reasons</li></ul>	<ul><li>○ UL Compliance Issue</li><li>○ EMC Compliance Issue</li><li>○ Software Change</li></ul>	<ul><li>New Feature</li><li>Quality Issue</li><li>Cosmetic Change</li></ul>	O Cost Reduction
REASON FOR CHANGE:  To document minor assembly procedures.			
DETAILS OF CHANGE:			

- 1. To facilitate assembly onto the board, the connectors at locations ATX1, ATX2, ATX3 and ATX4, on Rev 3 PCBs, need to be modified. The PCB insertion lug (polarisers) has to be cut off (removed) from one side only.
- 2. JP5 is a 5x2 header and Pin 1 needs to be cut or removed to form a keyway for polarisation purposes.