



ENGINEERING CHANGE NOTE:



ECN #: 404

ASSEMBLY: BMW4041D	DESCRIPTION: MW4-QDC Quad Digital Channel Card
New Assembly:	DATE: 18/01/01
Current Assy Rev: H 1H	Current Schematic Rev:
New Assy Rev: H 1H	New Schematic Rev:

☐ CMS BOMs Updated

☒ Excel BOMs Updated

☐ Subcontractor Records Updated

Compatibility Maintained: Yes

IMPLEMENTATION INFORMATION:

- ☐ Safety Issue
- ☐ UL Compliance Issue
- ☐ New Feature
- ☒ Cost Reduction
- ☐ Bug Fix
- ☐ EMC Compliance Issue
- ☐ Quality Issue
- ☐ Reliability Reasons
- ☐ Software Change
- ☐ Cosmetic Change

REASON FOR CHANGE:

Diodes D34 - D49 are not required. They were provided in case of undershoot which has not occurred.
The board's assembly revision remains unchanged.

DETAILS OF CHANGE:

Do not load D34 - D49 for new builds.
Do not remove from any existing boards.

.
HW or Project Engineer.....
.
R&D or Project Manager.....