ECN#

421

Page 1 of 1

## trivlight ENGINI

## **ENGINEERING CHANGE NOTE:**



ECN #: 4

ASSEMBLY: M New Assembly: Current Assy Rev: F New Assy Rev: J	MW4024	DESCRIPTION: DATE: Current Schematic Rev: New Schematic Rev:	MW4-QDC Chassis Assembly 02/07/01
CMS BOMs Updated	C Excel BOMs Updated C	Subcontractor Records Update	ted Compatibility Maintained: Yes
IMPLEMENTATION  Safety Issue  Bug Fix  Reliability Reasons	INFORMATION:  UL Compliance Issue EMC Compliance Issue Software Change	<ul><li>New Feature</li><li>Quality Issue</li><li>Cosmetic Change</li></ul>	○ Cost Reduction
REASON FOR CHANGE:  More reliable fitting of Rear Panel to Chassis			
2. Card Support Top 3. Chassis Assembly . NOTE TO PRODUCT NOTE TO SUBCOM	04 Rev 1 replaced with Rev. G  MMW4007 Rev 1 replaced w	to Issue 3. New part numbers by adding two M3 root	0.007 updated to Issue 2.  per for Chassis Assembly is MMW4024-J  nuts - IF POSSIBLE.