

ECN # 429

Page 1 of 1

**ENGINEERING CHANGE NOTE:**

mfx3

ECN #:

429

**ASSEMBLY:** MMW4010-H**DESCRIPTION:** MW4 Drive Bay Enclosure**New Assembly:** MMW4010-J**DATE:** 05/09/01**Current Assy Rev:** H**Current Schematic Rev:****New Assy Rev:** J**New Schematic Rev:**☐ CMS BOMs Updated☐ Excel BOMs Updated☐ Subcontractor Records Updated**Compatibility Maintained:** Yes**IMPLEMENTATION INFORMATION:**☐ Safety Issue☐ UL Compliance Issue☐ New Feature☒ Cost Reduction☐ Bug Fix☐ EMC Compliance Issue☐ Quality Issue☐ Reliability Reasons☐ Software Change☐ Cosmetic Change**REASON FOR CHANGE:**

To enable mounting of Hard Disk Drive inside the Enclosure without use of spacers.

**DETAILS OF CHANGE:**

1. Fold 4 mounting lugs inwards instead of outward.
2. Add screwdriver access holes.
3. Replace 90 degrees fold and 180 degrees fold with one 180 degree fold.
4. Drawing issue raised to 4.

.

NOTE TO PRODUCTION: No action on the existing stock.

.

NOTE TO FIELD SERVICE: No action required.