

**ENGINEERING CHANGE NOTE:**

ECN #:

448

ASSEMBLY: BMW4011**DESCRIPTION:** MW4-PXY CPU CARD**New Assembly:****DATE:** 04/03/02**Current Assy Rev:** U1 (or Lower)**Current Schematic Rev:** 5.14**New Assy Rev:** unchanged or alternatively U2**New Schematic Rev:** 5.14 (no change)

NOTE: THIS ECN APPLIES ONLY TO THE PXY CARDS WITH REV 5 PCB, THAT IS, ASSEMBLY LOWER THAN REV "V". REFER ECN449.

☐ CMS BOMs Updated☐ Excel BOMs Updated☐ Subcontractor Records Updated**Compatibility Maintained:** Yes**IMPLEMENTATION INFORMATION:**☐ Safety Issue☐ UL Compliance Issue☐ New Feature☐ Cost Reduction☐ Bug Fix☐ EMC Compliance Issue☐ Quality Issue☒ Reliability Reasons☐ Software Change☐ Cosmetic Change**REASON FOR CHANGE:**

1. Possible network problems if a Network Card with chip 82550 is used.

DETAILS OF CHANGE:

NOTE TO SYDNEY AND FIELD SERVICE: If the system exhibits network problems AND has PXY Card with assembly revision lower than Rev V, AND a Network Card with the chip 82550, then replace either the Network Card with one that uses chip 82558 or 82559, OR replace the PXY Card with a revision W or later (Refer ECN449).

ALTERNATIVELY: Implement the ECN449 and label the Card with Rev U2 (BMW4011E-U2).