ECN#

465

NOTE TO FIELD SERVICE: No action required

Page 1 of 1

Animinate Engineering Change Note:



ECN #: 4

ASSEMBLY:	BMW4062B-D DES	SCRIPTION: MW4-AES2 Interface Card	
New Assembly:	BMW4062B-E	DATE: 10/04/02	
Current Assy Rev:	D Current Sch	hematic Rev:	
New Assy Rev:	E New Sch	nematic Rev:	
NOTE: THIS ECN APPLIES ONLY TO THE CURRENT STOCK AND WIP HELD AT FAIRLIGHT, SYDNEY. THE ECN HAS BEEN INCORPORATED INTO BOM FOR FUTURE PRODUCTION.			
CMS BOMs Updated	d C Excel BOMs Updated C Subcontracte	or Records Updated Compatibility Maintained: Yes	
IMPLEMENTATION INFORMATION:			
○ Safety Issue	○ UL Compliance Issue ○ New	Feature • Cost Reduction	
• Bug Fix	○ EMC Compliance Issue ○ Oual	lity Issue	
Reliability Reason		netic Change	
REASON FOR CHANGE:			
DETAILS OF CHANGE:			
1. Remove 2 IC-s NC7SZ125M5 (STS5952) from locations U14 and U15			
2. Remove 4 Resistors 47R, 0603 from locations R57, R58, R62 and R63			
3. Add 2 Resistors 47R, 0603 (RMD0721) to locations R54 and R59			
4. Add 1 Resistor 0R, 0603 (RMD0075) to location R212			
5. Re-label the board assembly to read BMW4062B-E			
NOTE TO SUBCONTRACTORS: Amend documentation for future production .			
NOTE TO PROI	DUCTION: Modify all the existing stock and V	WIP of these boards	