ECN#

470

Page 1 of 1



ENGINEERING CHANGE NOTE:



CCN #:

			ECIVIII.
ASSEMBLY: New Assembly:	BMW4062B-E	DESCRIPTION: DATE:	MW4-AES2 Interface Card 6/05/2002
-		Current Schematic Rev:	0/03/2002
Current Assy Rev:			
New Assy Rev:	r	New Schematic Rev:	
CMS BOMs Updated	C Excel BOMs Updated	Subcontractor Records Upda	cted Compatibility Maintained: Yes
IMPLEMENTATION INFORMATION:			
○ Safety Issue	UL Compliance Issue	O New Feature	○ Cost Reduction
O Bug Fix	EMC Compliance Issu	e O Quality Issue	
• Reliability Reason	s O Software Change	Cosmetic Change	
REASON FOR CHANGE:			
DETAILS OF CHA	NGE:		
1. Replace two 10 RMD4379)	OR Resistors in locations R171 a	and R172 with two 100R, 0.0	063W, 50V, +/-1%, SMD0603 Resistors (FL P/N
2. Re-label the bo	oard so that it reads: BMW4062	B-F	
. NOTE TO SUBO	CONTRACTORS: Modify all th	e existing stock and WIP of	these boards and amend documentation for future
	NATIONAL NO. 11.1		
NOTE TO PROD	DUCTION: Modify all the existi	ng stock and WIP of these bo	oards.
NOTE TO FIELI	O SERVICE: No action required	i.	