ECN#

471

Page 1 of 1

## Anirhight Engineering Change Note:



ECN #: 47

			ECI (III
ASSEMBLY: B			MW4-AES1 Digital Input/Output Card
·			
Current Assy Rev: F	₹	<b>Current Schematic Rev:</b>	2.3
New Assy Rev: F	(unchanged)	New Schematic Rev:	2.3 (unchanged)
THIS ECN REPLACES ECN398.1			
CMS BOMs Updated	O Excel BOMs Updated	Subcontractor Records Updat	cted Compatibility Maintained: Yes
IMPLEMENTATION INFORMATION:			
Safety Issue	<b>UL Compliance Issue</b>	O New Feature	○ Cost Reduction
O Bug Fix	<b>EMC Compliance Issue</b>	e Ouality Issue	
Reliability Reasons	•	Cosmetic Change	
•		- Cosmetic Change	
REASON FOR CHANGE:  Cost saving by reducing the extent of ECN mods.			
DETAILS OF CHANGE:			
1. Cut off and remove pin 5 on U16 (74FCT244TQ).			
2. Connect RP4/3 to U14/39 or U16/5-Pad (not the pin) via a 100R resistor (there is a via-hole near RP4/3).			
3. Put solder blobs across J3 and J4 (raises the revision code to 2.3).			
4. Label the Board with the Revision Label that reads: BMW4061B-F.			
NOTE TO SUBCONTRACORS: Implement this ECN from the next manufacturing batch.			
NOTE TO PRODUCTION: No action required.			
. NOTE TO FIELD SERVICE: No action required.			