



ENGINEERING CHANGE NOTE:



ECN #: 477

ASSEMBLY:	BMW4131A-A	DESCRIPTION:	MW4-MADI Interface Card Standard Version
New Assembly:	BMW4131A-B	DATE:	29/05/02
Current Assy Rev:	A	Current Schematic Rev:	
New Assy Rev:	B	New Schematic Rev:	

☐ CMS BOMs Updated

☐ Excel BOMs Updated

☐ Subcontractor Records Updated

Compatibility Maintained: Yes

IMPLEMENTATION INFORMATION:

- ☐ Safety Issue
- ☐ UL Compliance Issue
- ☐ New Feature
- ☐ Cost Reduction
- ☐ Bug Fix
- ☐ EMC Compliance Issue
- ☐ Quality Issue
- ☐ Reliability Reasons
- ☐ Software Change
- ☐ Cosmetic Change

REASON FOR CHANGE:

To create a Standard Version of the MDI Card.

DETAILS OF CHANGE:

- Do not fit Toggle Switch (HSG1554) in location SW1.
- Do not fit 47R Resistors (RMD0721) in locations R2, R25 and R74.
- Fit 47R Resistors (RMD0721) in locations R1, and R75.
- Do not fit any Fibreoptic Transceiver in location FT1.
- Replace 10R Resistor (RMD1071) in location R56 with a 100R Resistor (RMD4379).
- Label the Board as BMW4131A-B.

NOTE TO SUBCONTRACTORS: NO ACTION REQUIRED.

NOTE TO PRODUCTION: NO ACTION REQUIRED.

NOTE TO FIELD SERVICE: NO ACTION REQUIRED.