

ECN # 498

Page 1 of 1

**ENGINEERING CHANGE NOTE:**

mfx3

ECN #: 498

ASSEMBLY: BMW4062B-F, BMW4081B-C,
BMIX041B-C**DESCRIPTION:** MW4-AI1card, AES2 card & AIB card**New Assembly:****DATE:** 22/07/2002**Current Assy Rev:** No Change**Current Schematic Rev:****New Assy Rev:** No Change**New Schematic Rev:**

☐ CMS BOMs Updated ☐ Excel BOMs Updated ☐ Subcontractor Records Updated **Compatibility Maintained** Yes

IMPLEMENTATION INFORMATION:

- ☐ Safety Issue ☐ UL Compliance Issue ☐ New Feature ☐ Cost Reduction
☐ Bug Fix ☐ EMC Compliance Issue ☐ Quality Issue
☐ Reliability Reasons ☐ Software Change ☐ Cosmetic Change

REASON FOR CHANGE:

CAP 220nF Ceramic Multilayer >=50V X7R is difficult to source but a 25V version is readily available.

DETAILS OF CHANGE:

1. Replace all, (CCE8907) CAP 220nF Ceramic Multilayer >=50V X7R with, (CCE8907) CAP 220nF Ceramic Multilayer >=25V X7R .