ECN#

345

Page 1 of 1

ENGINEERING CHANGE NOTE:



ASSEMBLY: BMW4081 DESCRIPTION: MW4- AI1 Analog Input 1 Card New Assembly: BMW4081B-C **DATE:** 27/03/00 Current Assy Rev: B **Current Schematic Rev: New Schematic Rev:** New Assy Rev: C Subcontractor Records Updated O CMS BOMs Updated Excel BOMs Updated **Compatibility Maintained:** Yes IMPLEMENTATION INFORMATION: ○ Safety Issue **UL Compliance Issue** O New Feature Ocost Reduction • Bug Fix **EMC Compliance Issue** Quality Issue • Reliability Reasons **Software Change** O Cosmetic Change **REASON FOR CHANGE:** Release of new revision of blank AI1 PCB (Rev B). **DETAILS OF CHANGE:** The AI1 blank PCB has been updated. The new PCB is Rev B and features the following changes: a) crosstalk reduced. b) LED moved to provide clearance for nearby connector.

Place a label on the card, marked "C", after the blank PCB P/N so it looks as follows BMW4081B-C