



ENGINEERING CHANGE NOTE:



ECN #: 369

ASSEMBLY: AMW4011

DESCRIPTION: MW4-PXY Module Assembly

New Assembly:

DATE: 31/05/00

Current Assy Rev: N/A

Current Schematic Rev:

New Assy Rev:

New Schematic Rev:

Applies from the introduction of PXY Support Bracket MMW4051 Revision 2.

CMS BOMs Updated

Excel BOMs Updated

Subcontractor Records Updated

Compatibility Maintained: Yes

IMPLEMENTATION INFORMATION:

Safety Issue

UL Compliance Issue

New Feature

Cost Reduction

Bug Fix

EMC Compliance Issue

Quality Issue

Reliability Reasons

Software Change

Cosmetic Change

REASON FOR CHANGE:

Reduce teh chance of damage to undersice tracks when mounting PCB assembly to metalwork.

DETAILS OF CHANGE:

1. New revision metalwork for MW4 is as follows;

MMW4051-2 PXY SUPPORT BRACKET D3.810.051 REVISION 2.

2. When using this new metalwork, also use the following nylon spacers on each of the mounting points;

MMW4060-A MW4 SPACER D3.810.060 REVISION 1.

3. Use all stock of previous revision PXY brackets before introducing the new revision metalwork.