ECN#

377.1

Page 1 of 1



ENGINEERING CHANGE NOTE:



ECN#:

I#: 377

ASSEMBLY: BMW4041D DESCRIPTION: MW4-QDC Quad Digital Channel Card **DATE:** 17/10/00 New Assembly: Current Assy Rev: G 1G **Current Schematic Rev:** New Assy Rev: H 1H **New Schematic Rev:** Subcontractor Records Updated CMS BOMs Updated Excel BOMs Updated **Compatibility Maintained:** Yes IMPLEMENTATION INFORMATION: O Safety Issue **UL Compliance Issue** O New Feature Ocst Reduction **Bug Fix EMC Compliance Issue** Ouality Issue • Reliability Reasons **Software Change** O Cosmetic Change **REASON FOR CHANGE:** Increase the number of audio channels the QDC can process.

DETAILS OF CHANGE:

- 1. Remove from BOM the following;
- 4 x SMM1560 SIMM 16MB 72p DRAM 60nS EDO
- 2. Add to BOM the following;
- 4 x SMM3254 SIMM 32M 72 DRAM 60n EDO SMALL

.

For Rev 1G boards place a assembly revision label after the blank PCB P/N on the card, marked "1H", so it reads as: "BMW4041D-1H"

For Rev G boards place a assembly revision label after the blank PCB P/N on the card, marked "H", so it reads as: "BMW4041D-H"

ECN377.1 is a correction to ECN377: Changed Current Assy Rev from "G" to "G 1G", New Assy Rev from "H" to "H 1H". Added assembly revision labelling details.