ECN#

380

Page 1 of 1

## Animinate Engineering Change Note:



ECN #: 38

ASSEMBLY: A New Assembly: Current Assy Rev: D New Assy Rev: E		DESCRIPTION: DATE: Current Schematic Rev: New Schematic Rev:	MW4-PS1 Power Supply Assembly 18/08/00
CMS BOMs Updated	Excel BOMs Updated	Subcontractor Records Updat	ed Compatibility Maintained: Yes
IMPLEMENTATION INFORMATION:			
<ul><li>Safety Issue</li><li>Bug Fix</li><li>Reliability Reasons</li></ul>	<ul><li>○ UL Compliance Issue</li><li>○ EMC Compliance Issue</li><li>○ Software Change</li></ul>	<ul><li>○ New Feature</li><li>● Quality Issue</li><li>○ Cosmetic Change</li></ul>	○ Cost Reduction
REASON FOR CHANGE:  Ensure the power supply does not shut down when using three or four QDCs populated with analogue I/O.			
DETAILS OF CHANGE:  1. Ensure the revision of the PCB assembly is BMW4021D-G.  2. Mark power supply with revision E to reflect the change of assembly.			