ECN#

393

Page 1 of 1

ENGINEERING CHANGE NOTE:



ECN #:

| ASSEMBLY: A New Assembly: Current Assy Rev: F New Assy Rev: G IN PROGRESS !!!! | !!!! | DESCRIPTION: DATE: Current Schematic Rev: New Schematic Rev: Subcontractor Records Update | MW4-PS1 Power Supply Assembly 31/10/00 ted Compatibility Maintained: Yes |
|---|--|---|---|
| IMPLEMENTATION Safety Issue Bug Fix Reliability Reasons | N INFORMATION: UL Compliance Issue EMC Compliance Issue Software Change | O New Feature O Quality Issue O Cosmetic Change | ○ Cost Reduction |
| REASON FOR CHANGE: Rectify UL non-compliance. | | | |
| DETAILS OF CHANGE: Remove the wire that runs from the IEC Mains Inlet Earth connector to the Mains Filter Earth conector. Fit a new wire with a 6mm Push-on connector on one end, and a Ring Terminal on the other. Connect this from the IEC Mains Inlet Earth connector to the PCB mounting point next to | | | |