ECN#

395

Page 1 of 1



ENGINEERING CHANGE NOTE:



ECN#:

	BMW4051D		MW4-CG5 Colour Graphics 5 CARD
New Assembly: E	BMW4051E	DATE:	09/11/00
Current Assy Rev: E	E (Current Schematic Rev:	
New Assy Rev: B	3	New Schematic Rev:	
CMS BOMs Updated	• Excel BOMs Updated •	Subcontractor Records Update	ted Compatibility Maintained: Yes
IMPLEMENTATION INFORMATION:			
○ Safety Issue	UL Compliance Issue	O New Feature	○ Cost Reduction
O Bug Fix	EMC Compliance Issue	Quality Issue	
• Reliability Reasons	-	Cosmetic Change	
REASON FOR CHANGE:			
Release of new revision of blank CG5 PCB (Rev E).			
DETAILS OF CHANGE:			
The CG5 blank PCB has been updated to eliminate modifications applied to PCB Rev D card. The new PCB is Rev E (P/N BMW4051E) and is equivalent to BMW4051D-E board. The assembly revision remains unchanged as Rev E. So the Assembled CG5 PCB's P/N should reads as: BMW4051E-E			
· · · · · · · · · · · · · · · · · · ·			
HW or Project Engineer			
R&D or Project Manager			