

**ENGINEERING CHANGE NOTE:**

mfx3

ECN #:

411

ASSEMBLY:

New Assembly: 1MFK48

DESCRIPTION: MW4-MFK48 Track Console**DATE:** 26/02/01**Current Assy Rev:****Current Schematic Rev:**

New Assy Rev: A

New Schematic Rev:

☐ CMS BOMs Updated ☐ Excel BOMs Updated ☐ Subcontractor Records Updated **Compatibility Maintained:** Yes

IMPLEMENTATION INFORMATION:

- ☐ Safety Issue ☐ UL Compliance Issue ☒ New Feature ☐ Cost Reduction
☐ Bug Fix ☐ EMC Compliance Issue ☐ Quality Issue
☐ Reliability Reasons ☐ Software Change ☐ Cosmetic Change

REASON FOR CHANGE:

1. Standard MFX3 Console have gradually evolved into 48 Track Console used with QDC Engine causing a need for change of the part number and new BOM

DETAILS OF CHANGE:

1. Release of a new documentation reflecting the introduction of the MFK 48 Track Console

HW or Project Manager: _____

R&D Manager: _____