

ECN # 419

Page 1 of 1

**ENGINEERING CHANGE NOTE:**

mfx3

ECN #:

419

ASSEMBLY: APS1611**DESCRIPTION:** MW4-PS1A Power Supply Assembly**New Assembly:****DATE:** 20/06/01**Current Assy Rev:****Current Schematic Rev:** N/A**New Assy Rev:** N/A**New Schematic Rev:**☐ CMS BOMs Updated☐ Excel BOMs Updated☐ Subcontractor Records Updated**Compatibility Maintained:** Yes**IMPLEMENTATION INFORMATION:**☐ Safety Issue☐ UL Compliance Issue☐ New Feature☐ Cost Reduction☐ Bug Fix☐ EMC Compliance Issue☐ Quality Issue☐ Reliability Reasons☐ Software Change☐ Cosmetic Change**REASON FOR CHANGE:**

Changes to Metalwork.

DETAILS OF CHANGE:

1. MMW4061 PS1 Base Plate Revision changed from 2 to 3 for the addition of two M4x10 studs. Drawing D3.810.061 updated to Rev 3.
2. MMW4065 PS1 Switch Panel modified by addition of the SS perforated piece spotwelded to the panel in place of punched ventilation holes. Drawing D3.810.065 updated to Rev 7.

NOTE TO SUBCONTRACORS: Continue with mods to the Base Plate on all current stock. The new stock of Rev 3 Base Plates will eliminated the need for the mods.