ECN#

422

Page 1 of 1

## \_twirlight

## **ENGINEERING CHANGE NOTE:**



ECN#:

ASSEMBLY:	MMW4025	DESCRIPTION:	MW4-Rear Panel Assembly
New Assembly:		DATE:	02/07/01
<b>Current Assy Rev:</b>	1	Current Schematic Rev:	
New Assy Rev:	J	New Schematic Rev:	
CMS BOMs Updated	Excel BOMs Updated	Subcontractor Records Upda	cted Compatibility Maintained: Yes
IMPLEMENTATION INFORMATION:			
○ Safety Issue	<b>UL Compliance Issue</b>	O New Feature	Ocost Reduction
O Bug Fix	<b>EMC Compliance Issue</b>	O Quality Issue	
• Reliability Reason	s O Software Change	O Cosmetic Change	
REASON FOR CHANGE:			
More reliable fitting of Rear Panel to Chassis			
DETAILS OF CHANGE:			
1. Rear Panel MMW4006 Rev 1 replaced with Rev. J. Drawing D3.810.006 updated to Issue 2.			
2. Rear Panel Assembly drawing D3.810.025 updated to Issue 3. New part number for Rear Panel Assembly is MMW4025-J			
NOTE TO PRODUCTION: Modify all existing stock by adding two 3.2 mm holes - IF ECN421 ON CHASSIS ASSEMBLY IS POSSIBLE TO CARRY OUT.			
NOTE TO SUBCONTRACTORS: Modify all existing stock by adding two 3.2 mm holes - IF ECN421 ON CHASSIS ASSEMBLY IS POSSIBLE TO CARRY OUT.			
NOTE TO FIELD SERVICE: No action required.			