ECN#

430

Page 1 of 1

## Join Line Engineering Change Note:



ECN #: 43

ASSEMBLY: N	MMW4035-2	DESCRIPTION:	MW4 PCB Retaining Strut
New Assembly: N	MMW4035-E	DATE:	05/09/01
Current Assy Rev: 2	2	<b>Current Schematic Rev:</b>	
New Assy Rev: B	3	New Schematic Rev:	
CMS BOMs Updated	C Excel BOMs Updated	Subcontractor Records Update	ted Compatibility Maintained: Yes
IMPLEMENTATION INFORMATION:			
○ Safety Issue	<b>UL Compliance Issue</b>	O New Feature	Cost Reduction
O Bug Fix	<b>EMC Compliance Issue</b>	e O Quality Issue	
• Reliability Reasons	_	Cosmetic Change	
REASON FOR CHANGE:			
To improve the rigidity of the assembly.			
DETAILS OF CHANGE:			
1. Remove all perforations.			
2. Add 5 mm Returns along two edges.			
3. Change material to 0.95 mm Stainless Steel, Finish: Natural			
NOTE TO PRODUCTION: Scrap the existing stock.			
NOTE TO FIELD SERVICE: No action required.			