ECN#

475

Page 1 of 1

twirlight

ENGINEERING CHANGE NOTE:



ECN #:

			-
	MMW4496 MMW4497	DESCRIPTION: DATE:	MW4 Fan Gasket 16/05/02
Current Assy Rev:	n/a	Current Schematic Rev:	
New Assy Rev:	n/a	New Schematic Rev:	
CMS BOMs Updated	C Excel BOMs Updated	O Subcontractor Records Upda	ted Compatibility Maintained: Yes
IMPLEMENTATION INFORMATION:			
O Safety Issue	UL Compliance Issue	New Feature	○ Cost Reduction
O Bug Fix	O EMC Compliance Iss		
O Reliability Reasons	•	Cosmetic Change	
REASON FOR CHANGE:			
ECN473.1			
DETAILS OF CHANGE:			
1. Cut out the a square section 86mm X 86mm out of the middle of the Fan Gasket MMW4496 so that it looks like a square window with 5mm thick frame.			
2 Book into stock as FL P/N MMW///97			

Book into stock as FL P/N MMW4497.

NOTE TO PRODUCTION: Modify all existing Stock and WIP. Gasket manufacturing tooling will be modified for future production.