ECN#

516

Page 1 of 1

Juilin Engineering Change Note:



ECN #: 51

ASSEMBLY:	BMW4001C-F	DESCRIPTION:	MW4-BPR Backplane
New Assembly:	BMW4001C-G	DATE:	23/09/02
Current Assy Rev:	F	Current Schematic Rev:	
New Assy Rev:	G	New Schematic Rev:	
CMS BOMs Updated	C Excel BOMs Updated	O Subcontractor Records Upda	ted Compatibility Maintained: Yes
IMPLEMENTATION INFORMATION:			
Safety Issue	UL Compliance Issue	O New Feature	○ Cost Reduction
O Bug Fix	EMC Compliance Issu	ie O Quality Issue	
Reliability Reason	s O Software Change	O Cosmetic Change	
REASON FOR CHANGE:			
DETAILS OF CHANGE:			
1. 48 Capacitors (CTD7046), 47uF, 16V in locations C5 C6 C7 C8 C13 C14 C15 C16 C21 C22 C23 C24 C29 C30 C31 C32 C37 C38 C39 C40 C45 C46 C47 C48 C53 C54 C55 C56 C61 C62 C63 C64 C65 C66 C67 C68 C69 C70 C71 C72 C73 C74 C75 C76 C77 C78 C79 C80 replaced with 47uF 20V Capacitors (CTD6911).			
2. New Board Assembly Revision: BMW4001C-G			
NOTE TO SUBCONTRACTORS: THIS ECN HAS BEEN INCORPORATED INTO BOM FOR THE FUTURE PRODUCTION.			
· · · · · · · · · · · · · · · · · · ·			
NOTE TO PRODUCTION: No action required.			
NOTE TO FIELD SERVICE: No action required.			