

ECN # 528

Page 1 of 1

**ENGINEERING CHANGE NOTE:**

mfx3

ECN #: 528

ASSEMBLY: MMW4038-F**DESCRIPTION:** Facia**New Assembly:** MMW4038-G**DATE:** 9/12/2002**Current Assy Rev:** Rev F**Current Schematic Rev:****New Assy Rev:** Rev G**New Schematic Rev:**

☐ CMS BOMs Updated ☐ Excel BOMs Updated ☐ Subcontractor Records Updated **Compatibility Maintained** Yes

IMPLEMENTATION INFORMATION:

- ☐ Safety Issue ☐ UL Compliance Issue ☐ New Feature ☐ Cost Reduction
☐ Bug Fix ☐ EMC Compliance Issue ☐ Quality Issue
☐ Reliability Reasons ☐ Software Change ☐ Cosmetic Change

REASON FOR CHANGE:

Hole size in Facia has been changed to increase airflow

DETAILS OF CHANGE:

1. DELETE MMW4038-F, Facia Panel, Rev F, Drawing # D3.810.038, Issue 3
.
2. ADD MMW4038-G, Facia Panel, Rev G, Drawing # D3.810.038, Issue 4
.
.

NOTE TO SUBCONTRACTORS: No Action required
.NOTE TO PRODUCTION: Consume current stock of MMW4038, then use MMW4038-G
.

NOTE TO FIELD SERVICE: A cooling Upgrade Kit will be available soon