

ECN # 542

Page 1 of 1

**ENGINEERING CHANGE NOTE:**

ECN #: 542

ASSEMBLY: AMW4011MOD**DESCRIPTION:** PXY Module**New Assembly:** AMW4011MOD**DATE:** 10/03/2003**Current Assy Rev:****Current Schematic Rev:****New Assy Rev:****New Schematic Rev:**☐ CMS BOMs Updated☐ Excel BOMs Updated☐ Subcontractor Records Updated**Compatibility Maintained** Yes**IMPLEMENTATION INFORMATION:**☐ Safety Issue☐ UL Compliance Issue☐ New Feature☐ Cost Reduction☐ Bug Fix☐ EMC Compliance Issue☐ Quality Issue☐ Reliability Reasons☐ Software Change☐ Cosmetic Change**REASON FOR CHANGE:**

SCSI card is no longer an option but standard with every PXY module

DETAILS OF CHANGE:

1. ADD HAD7128, SCSI Controller PCI

.

NOTE TO SUBCONTRACTORS: No action required.

.

NOTE TO PRODUCTION: Add this card to all PXY modules produced from March 2003 onward.

.

NOTE TO FIELD SERVICE: No action required.